




**Overview:** Part of spill impact on 8" Umuechem-Nkpoku Pipeline Right of Way at Omunwei. Picture was taken during Joint Investigation of 23<sup>rd</sup> June 2018.



**Close-up:** Illegal fitting on 8" Umuechem-Nkpoku Pipeline at Omunwei Picture was taken during Joint Investigation of 23<sup>rd</sup> June 2018.