




Overview: Part of spill impact on 18" Assa – Rumuekpe Pipeline Right of Way at Omudioga. .
Picture was taken during Joint Investigation of 3rd July 2018.



Close-up: Tampered 5th Bolt/Nut on 18" Assa – Rumuekpe Pipeline at Omudioga. Picture was taken during Joint Investigation of 3rd July 2018.