


Overview: Part of spill impact on 14" Okordia-Rumuekpe Pipeline Right of Way at Ikarama. Picture was taken during Joint Investigation of 16<sup>th</sup> July 2018.



Close-up: Hacksaw Cut on 14" Okordia-Rumuekpe Pipeline at Ikarama. Picture was taken during Joint Investigation of 16<sup>th</sup> July 2018.