




Overview: Part of spill impact on 28" Nkpoku - Bomu Pipeline at Rumuokwurusi. Picture was taken during Joint Investigation of 9th July 2018.



Close-up: Illegal Fittings on 28" Nkpoku - Bomu Pipeline at Rumuokwurusi. Picture was taken during Joint Investigation of 24th July 2018.