



**Overview:** Part of spill impact on 20''Rumuekpe-Nkpoku Pipeline Right of Way at Mbodo-Aluu. Picture was taken during Joint Investigation of 15<sup>th</sup> March 2018.



**Close-up:** One of three Illegal fittings on 20''Rumuekpe-Nkpoku Pipeline at Mbodo-Aluu. (The other two were non-leaking).