


Overview: Part of spill impact on 16" NunRiver-Kolocreek Pipeline at Oporoma. Picture was taken during Joint Investigation of 28th March 2018.



Close-up: Corrosion (pin hole on) 16" NunRiver-Kolocreek Pipeline at Oporoma. Picture was taken during Joint Investigation of 30th March 2018.