



Overview: Part of spill impact on 20" Kolocreek-Rumuekpe Pipeline at Odau_KM 19. Picture was taken during Joint Investigation of 26th March 2018.



Close-up: Illegal fitting on 20" Kolocreek-Rumuekpe Pipeline at Odau_KM 19. Picture was taken during Joint Investigation of 26th March 2018.



Close-up: Illegal Pipe connection running from 20" Kolocreek-Rumuekpe Pipeline at Odau_KM 19. Picture was taken during Joint Investigation of 26th March 2018.