


**Overview:** Part of spill impact on Agbaya Well1 Well Head at Agbayama Ogbotobo. Picture was taken during Joint Investigation of 3<sup>rd</sup> March 2018.



**Close-up:** Tampered Survey Cap on Agbaya Well1 Well Head at Agbayama Ogbotobo. Picture was taken during Joint Investigation of 3<sup>rd</sup> March 2018.