



Overview: Part of spill impact on Benisede Well-5T Flowline at Ojobo. Picture was taken during Joint Investigation of 19th April 2018.



Close-up: Inward Dent & Tear on Benisede Well-5T Flowline at Ojobo. Picture was taken during Joint Investigation of 19th April 2018.