




**Overview:** Part of spill impact on 28" Bomu-Bonny Pipeline at Ayambo-Bonny . Picture was taken during Joint Investigation of 18<sup>th</sup> March 2018.



**Close-up:** Illegal fitting on 28" Bomu-Bonny Pipeline at Ayambo-Bonny . Picture was taken during Joint Investigation of 18<sup>th</sup> March 2018.