



| | | | |
|--|--|-------------------|----------------------|
| | | E 6.660466 | Date 2018/11/09 |
| | | N 4.974023 | Time 14:53:03 +01:00 |
| | | Altitude 14.400 M | Speed 0.02 KPH |

Overview: Part of spill impact on 20" Kolocreek - Rumuekpe Pipeline at Okoma-1
 Picture was taken during Joint Investigation of 9th November 2018.



| | | | |
|--|--|------------------|----------------------|
| | | E 6.660513 | Date 2018/11/09 |
| | | N 4.974013 | Time 15:53:49 +01:00 |
| | | Altitude 9.700 M | Speed 0.01 KPH |

Close up: Illegal fitting on 20" Kolocreek - Rumuekpe Pipeline at Okoma-1.
 Picture was taken during Joint Investigation of 9th November 2018.