


**Overview:** Part of spill impact on 20" Kolocreek - Rumuekpe Pipeline at Okoma-1  
 Picture was taken during Joint Investigation of 10<sup>th</sup> November 2018.



**Close up:** Illegal fitting on 20" Kolocreek - Rumuekpe Pipeline at Okoma-1.  
 Picture was taken during Joint Investigation of 10<sup>th</sup> November 2018.