




**Overview:** Part of spill impact on 28" Nkpoku – Bomu Pipeline Right of Way at Kporghor. Picture was taken during Joint Investigation of 23rd November 2018.



**Close-up:** Illegal Fitting on 28" Nkpoku – Bomu Pipeline at Kporghor. Picture was taken during Joint Investigation of 23rd November 2018.