


Overview: Part of spill impact on 4" Obele – Ibaa Pipeline Right of Way at Ibaa . Picture was taken during Joint Investigation of 29th November 2018.



Close-up: Hacksaw Cut on 4" Obele – Ibaa Pipeline at Ibaa. Picture was taken during Joint Investigation of 29th November 2018.