




**Overview:** Part of spill impact on 24" Nkpoku - Bomu Pipeline Right of Way at Bara-alue .  
 Picture was taken during Joint Investigation of 18<sup>th</sup> November 2018.



**Close-up:** Internal Corrosion on 24" Nkpoku - Bomu Pipeline at Bara-alue Picture was taken during Joint Investigation of 18<sup>th</sup> November 2018.