



Overview: Part of spill impact on 24" Bomu-Bonny Pipeline Right of Way at Owokiri. Picture was taken during Joint Investigation of 28th November 2018.



Close-up: Illegal fitting on 24" Bomu-Bonny Pipeline at Owokiri. Picture was taken during Joint Investigation of 28th November 2018.