



Overview: Part of spill impact on 28" Bomu - Bonny Pipeline Right of Way at Owokiri. Picture was taken during Joint Investigation of 27th November 2018.



Close-up: Illegal fitting on 28" Bomu - Bonny Pipeline at Owokiri. Picture was taken during Joint Investigation of 27th November 2018.