




Overview: Part of spill impact on 24" Nkpoku - Bomu Pipeline Right of Way at Egbalor. Picture was taken during Joint Investigation of 29th November 2018.



Close-up: Hacksaw Cut on 24" Nkpoku - Bomu Pipeline at Egbalor. Picture was taken during Joint Investigation of 4th December 2018.