



Overview: Part of spill impact on 20" Kolocreek - Rumuekpe Pipeline Right of Way at Okporowo. Picture was taken during Joint Investigation of 15th November 2018.



Close-up: Hacksaw Cuts on 20" Kolocreek - Rumuekpe Pipeline Right of Way at Okporowo. Picture was taken during Joint Investigation of 20th November 2018.