



Overview: Part of spill impact on 24" Nkpoku-Bomu Pipeline Right of Way at Bera. Picture was taken during Joint Investigation of 5th September 2018.



Close-up: Drilled Hole on 24" Nkpoku-Bomu Pipeline at Bera. Picture was taken during Joint Investigation of 5th September 2018.