




**Overview:** No spill impact on 36" Nkpoku-Bomu Pipeline Right of Way at Rumuesara-Eneka. Picture was taken during Joint Investigation of 11<sup>th</sup> September 2018.



**Close-up:** Illegal fitting on 36" Nkpoku-Bomu Pipeline at Rumuesara-Eneka. . Picture was taken during Joint Investigation of 13<sup>th</sup> September 2018.