




Overview: Part of spill impact on 20'' Otumara-Escravos Pipeline Right of Way at Ugboegungun. Picture was taken during Joint Investigation of 9th September 2018.



Close-up: Illegal fitting on 20'' Otumara-Escravos Pipeline at Ugboegungun. Picture was taken during Joint Investigation of 9th September 2018