


Overview: Part of spill impact on 14" Okordia-Rumuekpe Pipeline Right of Way at Akaramini. Picture was taken during Joint Investigation of 8th September 2018.



Close-up: Illegal fitting on 14" Okordia-Rumuekpe Pipeline at Akaramini. Picture was taken during Joint Investigation of 8th September 2018.