




**Overview:** Part of spill impact on 16" Egbema-Assa Pipeline Right of Way at Assa. Picture was taken during Joint Investigation of 18<sup>th</sup> September 2018.



**Close-up:** Illegal fittings on 16" Egbema-Assa Pipeline at Assa. Picture was taken during Joint Investigation of 18<sup>th</sup> September 2018.