


Overview: Part of spill impact on 18'' Assa – Rumuekpe Pipeline Right of Way at Akpabu. Picture was taken during Joint Investigation of 26th September 2018.



Close up: Illegal fittings on 18'' Assa – Rumuekpe Pipeline at Akpabu. Picture was taken during Joint Investigation of 26th September 2018.