


**Overview:** Part of spill impact on 20" Kolocreek – Rumuekpe Pipeline Right of Way at Odau.  
 Picture was taken during Joint Investigation of 29<sup>th</sup> September 2018.



**Close up:** Illegal fitting on 20" Kolocreek – Rumuekpe Pipeline at Odau.  
 Picture was taken during Joint Investigation of 29<sup>th</sup> September 2018.