



**Overview:** Part of spill impact on 4" Diebu Creek Closed Drain Vessel Flange at Peremabiri. Picture was taken during Joint Investigation of 25<sup>th</sup> September 2018.



**Close up:** Failed Flange on 4" Diebu Creek Closed Drain Vessel Flange at Peremabiri. Picture was taken during Joint Investigation of 25<sup>th</sup> September 2018.