




Overview: Part of spill impact on 16" Nun River - Kolocreek Pipeline Right of Way at Otuegwel. Picture was taken during Joint Investigation of 14th April 2019.



Close-up: Failed Clamp on 16" Nun River - Kolocreek Pipeline at Otuegwel. Picture was taken during Joint Investigation of 14th April 2019