




**Overview:** Part of spill impact on 12" Imo River 2 - Ogale Pipeline Right of Way at Igiuikwu-Owaza. Picture was taken during Joint Investigation of 12<sup>th</sup> April 2019.



**Close-up:** Plugged Drilled Hole on 12" Imo River 2 - Ogale Pipeline at Igiuikwu-Owaza. Picture was taken during Joint Investigation of 12<sup>th</sup> April 2019