




Overview: Part of spill impact on 12" Imo River 2 - Ogale Pipeline Right of Way at Igiriukwu-Owaza. Picture was taken during Joint Investigation of 11th April 2019.



Close-up: Illegal Fitting on 12" Imo River 2 - Ogale Pipeline at Igiriukwu-Owaza. Picture was taken during Joint Investigation of 11th April 2019