




**Overview:** Part of spill impact on 18" Assa – Rumuekpe Pipeline Right of Way at Ochia-Awarra. Picture was taken during Joint Investigation of 18<sup>th</sup> April 2019.



**Close-up:** Illegal Fitting on 18" Assa – Rumuekpe Pipeline at Ochia-Awarra. Picture was taken during Joint Investigation of 18<sup>th</sup> April 2019



Close-up: Sand bag and Concrete concealing theft point on 18" Assa – Rumuekpe Pipeline at Ochia-Awarra. Picture was taken during Joint Investigation of 18<sup>th</sup> April 2019