




Overview: Part of spill impact on 18" Assa – Rumuekpe Pipeline Right of Way at Elele-Alimini. Picture was taken during Joint Investigation of 18th April 2019.



Close-up: leaking Illegal Fitting on 18" Assa – Rumuekpe Pipeline at Elele-Alimini. Picture was taken during Joint Investigation of 18th April 2019