




Overview: Part of spill impact on 24" Nkpoku – Bomu Pipeline Right of Way at Egbalor. Picture was taken during Joint Investigation of 22nd April 2019.



Close-up: Leaking Illegal fitting on 24" Nkpoku – Bomu Pipeline at Egbalor. Picture was taken during Joint Investigation of 22nd April 2019