




Overview: Part of spill impact on 12" Imo River – Ogale Pipeline Right of Way at Ogale. Picture was taken during Joint Investigation of 20th April 2019.



Close-up: Illegal Fitting on 12" Imo River – Ogale Pipeline at Ogale. Picture was taken during Joint Investigation of 20th April 2019