




Overview: Part of spill impact on 24" Bomu – Bonny Pipeline Right of Way at Patrick Waterside. Picture was taken during Joint Investigation of 10th April 2019.



Close-up: Hack Saw Cuts on 24" Bomu – Bonny Pipeline at Patrick Waterside. Picture was taken during Joint Investigation of 12th April 2019