



Overview: Part of spill impact on 10" Diebu – Nunriver Pipeline Right of Way at Onyoma / Ekowe. Picture was taken during Joint Investigation of 27th April 2019.



Close-up: Plugged Hack Saw Cut on 10" Diebu – Nunriver Pipeline at Onyoma / Ekowe. Picture was taken during Joint Investigation of 27th April 2019