




Overview: Part of spill impact on 24" Bomu – Bonny Pipeline Right of Way at Kpor. Picture was taken during Joint Investigation of 25<sup>th</sup> April 2019.



Close-up: Illegal fitting on 24" Bomu – Bonny Pipeline at Kpor. Picture was taken during Joint Investigation of 25<sup>th</sup> April 2019