


Overview: Part of spill impact on 14" Okordia - Rumuekpe Pipeline Right of Way at Ukpeliède. Picture was taken during Joint Investigation of 28<sup>th</sup> April 2019.



Close-up: Illegal fitting on 14" Okordia - Rumuekpe Pipeline at Ukpeliède. Picture was taken during Joint Investigation of 28<sup>th</sup> April 2019