




Overview: Part of spill impact on 12'' Imo River2 – Ogale Pipeline Right of Way at Komkom. Picture was taken during Joint Investigation of 30th April 2019.



Close-up: Illegal Fittings on 12'' Imo River2 – Ogale Pipeline at Komkom. Picture was taken during Joint Investigation of 30th April 2019