




**Overview:** Part of spill impact on 12" Imo River – Ogale Pipeline Right of Way at Komkom. Picture was taken during Joint Investigation of 30<sup>th</sup> April 2019.



**Close-up:** Illegal Fittings on 12" Imo River – Ogale Pipeline at Komkom. Picture was taken during Joint Investigation of 30<sup>th</sup> April 2019