



Overview: Part of spill impact on 16" Egbema - Assa Pipeline Right of Way at Obile. Picture was taken during Joint Investigation of 9th April 2019.



Close-up: Illegal fitting on 16" Egbema - Assa Pipeline at Obile. Picture was taken during Joint Investigation of 9th April 2019