



Overview: Part of spill impact on 6'' Tunu Kanbo Well 7L Flowline at Egbemo-Analabiri-agbidiana. Picture was taken during Joint Investigation of 9th May 2019.



Close-up: Hack Saw Cuts on 6'' Tunu Kanbo Well 7L Flowline at Egbemo-Analabiri-agbidiana. Picture was taken during Joint Investigation of 9th May 2019.