



**Overview:** Part of spill impact on 4" Opukushi Well 33L/S Flowline at Egbemo-Analabiri-agbidiana. Picture was taken during Joint Investigation of 7<sup>th</sup> May 2019.



**Close-up:** Missing part of the Flowline on 4" Opukushi Well 33L/S Flowline at Egbemo-Analabiri-agbidiana. Picture was taken during Joint Investigation of 7<sup>th</sup> May 2019.