




Overview: Part of spill impact on 20'' Kolocreek – Rumuekpe Pipeline Right of Way at Odau. Picture was taken during Joint Investigation of 23rd May 2019



Close-up: Illegal fitting on 20'' Kolocreek – Rumuekpe Pipeline at Odau. Picture was taken during Joint Investigation of 23rd May 2019