Overview: Part of spill impact on 12" Imo River1 – Ogale Pipeline Right of Way at Ogale Picture was taken during Joint Investigation of 24th August 2019.




Close-up: Illegal fitting on 12" Imo River1 – Ogale Pipeline at Ogale . Picture was taken during Joint Investigation of 24th August 2019.