




Overview: Part of spill impact on 8inch Nkali Imo River 2 Delivery Line at Nkali . Picture was taken during Joint Investigation of 6th December 2019.



Close-up: Illegal fitting on 8inch Nkali Imo River 2 Delivery Line at Nkali . Picture was taken during Joint Investigation of 6th December 2019.