



Overview: Part of spill impact on 14" Okordia – Rumuekpe Pipeline Right of Way at Ikata. Picture was taken during Joint Investigation of 9th December 2019.



Close-up: Illegal Fitting on 14" Okordia – Rumuekpe Pipeline at Ikata . Picture was taken during Joint Investigation of 9th December 2019.