



Overview: Part of spill impact on 18inch Assa Rumuekpe Pipeline Right of Way at Umudioga-Akpabu. Picture was taken during Joint Investigation of 13th December 2019.



Close-up: Plugged illegal fittings on 18inch Assa Rumuekpe Pipeline at Umudioga/Akpabu. Picture was taken during Joint Investigation of 14th December 2019.