


**Overview:** Part of spill impact on 12inch ImoRiver1 - Ogale Pipeline Right of Way at Umuololo. Picture was taken during Joint Investigation of 16<sup>th</sup> December 2019.



**Close-up:** Illegal fitting 12inch ImoRiver1 - Ogale Pipeline at Umuololo. Picture was taken during Joint Investigation of 16<sup>th</sup> December 2019.