




**Overview:** Part of spill impact on 20'' Kolocreek – Rumuekpe Pipeline Right of Way at Odau-KP9. Picture was taken during Joint Investigation of 11<sup>th</sup> December 2019.



**Close-up:** Leaking Illegal Fitting on 20'' Kolocreek – Rumuekpe Pipeline at Odau-KP9. Picture was taken during Joint Investigation of 19<sup>th</sup> December 2019